## Replacement Sheet



10






FIG. 2




FIG. 3A





FIG. 3B



## Replacement Sheet



FIG. 4A





FIG. 4B






FIG. 6A




FIG. 6B





FIG. 6C



## Replacement Sheet ....



FIG. 7A




FIG. 7B




FIG. 8A




FIG. 8B





FIG. 9








FIG. 10




FIG. 11






FIG. 12








FIG. 14

					<u> </u>	
Number of Cycles	100	200	400	600	800	1000
Connecting Member 20a	0/88	0/88	0/88	0/88	0/88	0/88
Connecting Member 20b	0/88	0/88	0/88	0/88	0/88	0/88
Connecting Member 20c	0/88	0/88	0/88	0/88	0/88	0/88
Connecting Member 20d	0/88	0/88	0/88	0/88	0/88	0/88
Connecting Member 20e	0/88	0/88	0/88	0/88	0/88	0/88
Connecting Member 20f	0/88	0/88	0/88	0/88	0/88	0/88
Sparkle Ball S-type	0/88	0/88	0/88	0/88	8/88	15/88
Sparkle Ball C-type	0/88	0/88	2/88	8/88	10/88	12/88
Coper Ball	0/88	0/88	1/88	5/88	12/88	13/88

MAR 0 1 2004

FIG. 15 (PRIOR ART)




FIG. 16 (PRIOR ART)




FIG. 17 (PRIOR ART)

